

City of Detroit
Department of Recreation Performance Audit
Exhibit 6 – Adams/Butzel Center

Overall Evaluation – Poor Condition

- Significant amount of trash and debris appeared to have been there for some time.
- Grass was a reasonable height.
- Equipment (two slides, two swing sets, one climbing structure) was old with chipped and peeling paint – no shock absorbent surfaces around or below equipment.
- Of the twelve swings, three were broken, none were missing.
- Exposed concrete around the base of the slides.



General appearance of the playground, trash scattered throughout.

City of Detroit
Department of Recreation Performance Audit
Exhibit 6 – Adams/Butzel Center



Slide with exposed concrete at the base, equipment was old with chipped paint and no safety surface beneath the slide.



Old equipment with chipped paint, no safety surfaces and scattered trash.

City of Detroit
Department of Recreation Performance Audit
Exhibit 6 – Adams/Butzel Center



Climbing structure with chipped and peeling paint and no safety surfaces. Trash was scattered throughout.